

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to:

Commissioner for Patents

United States Patent & Trademark Office Attention: Certificate of Correction Branch

P.O. Box 1450

Alexandria, VA 22313-1450, on

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Jason S. Morrow

Group Art Unit: 3612

In re application of

Dinesh C. Seksaria et al. FRONT END APRON ASSEMBLY

: FOR A MOTOR VEHICLE

Serial No. 10/816,501

Certificate MAY 3 1 2005 Filed: April 1, 2004

Patent No. 6,886,886 B2

of Correction

Issued: May 3, 2005

: ATTORNEY DOCKET: 370050-00002-5

LETTER

600 Grant St., 44th Floor Pittsburgh, PA 15219 May 23, 2005

Commissioner for Patents United States Patent & Trademark Office Attention: Certificate of Correction Branch P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

In comparing the above-identified original patent document with the original papers filed in the Patent and Trademark Office, we have noted ten (10) errors which were the printer's errors.

It is respectfully requested that a Certificate of Correction be issued to correct these printing errors in the above-identified patent.

(412) 566-6965

Respectfully submitted,

Grant E. Coffield

Registration No. 52,758

Attorney for Applicant

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

6,886,886 BZ_

DATED

May 3, 2005

INVENTOR(S):

Dinesh C. Seksaria et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 3, line 64, insert --, -- after "members".

Col. 6, line 23, "owing" should read -- the following--.

Col. 6, line 24, insert --parts are-- after "like".

Col. 9, line 53, insert --side 118-- after "first".

Col. 11, line 45, insert --the-- after "by".

Col. 11, line 52, delete "(not yet assigned)", insert -- (10/271,449)--.

Col. 12, line 58, "304,306" should read --304, 306--.

Col. 15, line 59, "gassembly" should read --assembly--.

Col. 15, lines 61 & 64, "200-100" should, in both instances, read --200-400--.

1 of 1

MAILING ADDRESS OF SENDER:

Sally Novosel, Docket Administrator ECKERT SEAMANS CHERIN & MELLOTT, LLC 600 Grant Street, 44th Floor Pittsburgh, PA 15219 PATENT NO. 6,886,886 137_

No. of add'l. copies

@ 50¢ per page

 \Rightarrow

PORTER U.S. POSTAGE

United States Patent & Trademark Office Correction Branch Confice Correction Branch Mail Stop: Certificate of Correction Correction